


## MAȘINĂ DE FASONAT SIMPLĂ P34, P38, P44, P54, P56, P74



| Model                 | ÎNDOIRI PE MINUT | CP/KW   | 65 KG/MM <sup>2</sup><br>MM      | 85 KG/MM <sup>2</sup><br>MM      | DIMENSIUNI<br>CM | GREUTATE<br>KG |
|-----------------------|------------------|---------|----------------------------------|----------------------------------|------------------|----------------|
| P34<br>220 V<br>380 V | 11               | 3/2.2   | 1Ø 30 mm<br>2Ø 22 mm<br>3Ø 18 mm | 1Ø 28 mm<br>2Ø 20 mm<br>3Ø 16 mm | 75x80x85         | 285            |
| P38<br>220 V<br>380 V | 9                | 4/3     | 1Ø 34 mm<br>2Ø 26 mm<br>3Ø 20 mm | 1Ø 32 mm<br>2Ø 24 mm<br>3Ø 18 mm | 86x90x85         | 320            |
| P44<br>220 V<br>380 V | 6                | 4/3     | 1Ø 38 mm<br>2Ø 30 mm<br>3Ø 24 mm | 1Ø 36 mm<br>2Ø 28 mm<br>3Ø 22 mm | 105x95x89        | 469            |
| P54<br>380 V          | 6                | 5.5/4   | 1Ø 44 mm<br>2Ø 34 mm<br>3Ø 28 mm | 1Ø 40 mm<br>2Ø 32 mm<br>3Ø 24 mm | 105x95x89        | 582            |
| P56<br>380 V          | 5                | 7.5/5.5 | 1Ø 46 mm<br>2Ø 36 mm<br>3Ø 30 mm | 1Ø 42 mm<br>2Ø 34 mm<br>3Ø 26 mm | 130x95x89        | 676            |
| P74<br>380 V          | 5                | 10/7.5  | 1Ø 60 mm<br>2Ø 42 mm<br>3Ø 34 mm | 1Ø 50 mm<br>2Ø 36 mm<br>3Ø 30 mm | 160x116x96       | 1650           |